






Period of responsibility begins with the granting of a licence, and continues until In the opinion of HSE there has ceased to be any danger from ionising radiations from anything on the site (or part thereof) Or A new nuclear site licence is granted in respect of the site























Example RS-G-1.7 values		HSE
H3 Cs137 Co60 Pu Sr90 C14	100 Bq/g 0.1 Bq/g 0.1 Bq/g 0.1 Bq/g 1 Bq/g 1 Bq/g	



